

IECEx Quality Assessment Report Summary

Page 1 of 1

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: GB/SIR/QAR09.0012/12

QAR Free Ref. No.: 80085798/99/800 Status:Issued

Details of change: Recertification Audit Date of issue: 2021-09-17

Site(s) audited: ADS LLC Valid until:2024-08-13

340 The Bridge Street
Suite 204
Audit date: 2021-07-23
Huntsville

USA

Alabama 35806

United States of America

Issuing ExCB: SIR - CSA Group Testing UK Ltd

Manufacturer: ADS LLC

340 The Bridge Street

Suite 204 Huntsville Alabama 35806

USA

Location of United States of America

Manufacturer:

Product information: Sensors, transducers and signalling switches, instrumentation, measurement and control equipment.

Protection concept: Ex ia, ib

Related QARs:

 GB/SIR/QAR09.0012/00
 GB/SIR/QAR09.0012/01
 GB/SIR/QAR09.0012/02

 GB/SIR/QAR09.0012/03
 GB/SIR/QAR09.0012/04
 GB/SIR/QAR09.0012/05

 GB/SIR/QAR09.0012/06
 GB/SIR/QAR09.0012/07
 GB/SIR/QAR09.0012/08

 GB/SIR/QAR09.0012/09
 GB/SIR/QAR09.0012/10
 GB/SIR/QAR09.0012/11

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for previous versions:

IECEx SIR 09.0020X issue: 0 IECEx SIR 09.0020X issue: 1 IECEx SIR 09.0020X issue: 2 IECEx SIR 09.0020X issue: 3 IECEx SIR 09.0020X issue: 4 IECEx SIR 09.0020X issue: 5 IECEx SIR 09.0020X issue: 6 IECEx SIR 09.0020X issue: 7 IECEx SIR 09.0020X issue: 8 IECEx SIR 09.0020X issue: 9 IECEx SIR 09.0020X issue: 10 IECEx SIR 09.0020X issue: 11 IECEx SIR 09.0020X issue: 12 IECEx SIR 09.0020X issue: 13 IECEx SIR 09.0020X issue: 14 IECEx SIR 09.0020X issue: 15 IECEx SIR 09.0020X issue: 16 IECEx SIR 09.0020X issue: 17 IECEx SIR 09.0020X issue: 18 IECEx SIR 09.0020X issue: 19 IECEx SIR 09.0021X issue: 0 IECEx SIR 09.0021X issue: 1 IECEx SIR 09.0021X issue: 2 IECEx SIR 09.0021X issue: 3 IECEx SIR 09.0021X issue: 4 IECEx SIR 16.0043X issue: 0 IECEx SIR 16.0043X issue: 1 IECEx SIR 16.0043X issue: 2

Comments: